




## NoiseTools 软件如何移除 不需要的突发干扰等噪声

适用doseBadge个体噪声暴露计及optimus声级计


# NoiseTools 软件

- 打开NoiseTools软件,doseBadge读数器或者optimus声级计通过USB连接线连接到PC上,完成数据下载.
- 软件NoiseTools选择右侧'时间历史'按键,在图中可根据需要标记出需要标记的噪声段,可多处标记.操作为:左键选择需要标记噪声区域,右键标记其为一种颜色,命名一个任意名称,例如 1,2,3.如下图红绿蓝标记所示.
- 标记后把鼠标放图上会从上至下依次出现鼠标点的Leq值等信息,Default触发时间段的Leq值等信息(如果在绿色声级计里设置了),以及标记部分的Leq值等信息.




# NoiseTools 软件

- 在时间历史图表中,图左侧有图标地方用鼠标单击,可根据需要多选各种测量数据.如下图所示,这些数据  
的计算都会反应到图表和标记中.



# NoiseTools 软件

- 在右侧”时间历史”按钮处,鼠标按下时间长一些,就出现了’标记’,然后选择按下,即出如下图.
- 会有刚才标记的不同颜色和名称的不同时段的噪声列表,可自行选加号减号移除或添加.下方剩余功能部分会自动计算剔除标记噪声后的剩余噪声的Leq等值的情况.



The screenshot shows the NoiseTools software interface. The main window displays a table of noise measurements with columns for start/end time, label, and various noise metrics. A sidebar on the left contains navigation options like '收藏夹', '地点', '人物', '项目', and '设备'. A right sidebar contains action buttons like '总结工作噪音', '时间历史标记', '频率频段', and '频率分析'. A context menu is open over the '时间历史标记' button, showing options for 'Graph' and '标记'.

开始	结束	标签	LAeq (dB)	LCPeak (dB)	LAFMax (dB)	31.5 Hz (dB)	6.3 Hz3 (dB)	行动
8:34:26	8:36:56	1	34.1	82.9	53.9	53.6	41.0	[Red]
8:38:36	8:41:57	2	51.7	85.7	57.5	57.0	48.8	[Green]
8:43:33	8:44:06	3	36.9	80.6	51.8	56.3	51.0	[Blue]

剩余	45.6	86.7	57.5	56.7	48.6
总体	0	0.0	0.0	0	0



# Questions?



# Cirrus Research plc

Acoustic House  
Bridlington Road  
Hunmanby  
North Yorkshire  
YO14 0PH

T: 01723 891655

F: 01723 891742

E: [sales@cirrusresearch.co.uk](mailto:sales@cirrusresearch.co.uk)

W: [www.cirrusresearch.co.uk](http://www.cirrusresearch.co.uk)



ISO 14001:2004  
EMS 552104

ISO 9001:2008  
FM 531001

**Cirrus北京联系方式:**

**电话: 13520657953**

**Email: sales@cirrusresearch.cn**

**QQ : 1975264718**

